RDX QuikStor Utility Release Notes

RDX QuikStor Utility Version 1.61

Improvements:

- Updated utility to support the new RDX QuikStor SATA III drive model.
- Added a dialog box when updating firmware on RDX QuikStor SATA I drive to version 0080 or greater
    - Warning: SATA firmware 0080 has special requirements for HBA support. Please ensure your SATA HBA configuration is supported before continuing with this firmware update."
    - "Please refer to KB # D3648A72 for more information."

Other Fixes:

- Improve the Change Firmware progress bar function.